


CS-WINDOWKIT-G3

Blue filter


- Rychlá a snadná montáž
- For the assembly at CS 50
- For contrast enhancement
- Blue filter



Safety instructions

The Instruments are not to be used for safety applications, in particular applications in which safety of persons depends on proper operation of the instruments.

These instruments shall exclusively be used by qualified personnel.



TECHNICAL INFORMATION (typ.)

+20°C, 24V DC

P ípevn ní

4 otvory

Vhodné pro

CS 50

Materiál pouzdra

Plast

Tightening torque

max. 0,1 Nm